

TABLE OF CONTENTS

	Page
DISCLAIMER	I
ACKNOWLEDGMENTS	ii
PAVEMENT CONDITION RATING PROCEDURES	1
INTRODUCTION	1
FIELD MONITORING PROCEDURE	4
PAVEMENT CONDITION RATING FORMS AND KEY FORMS	5
Key - Flexible Pavement Condition Rating Form	6
Flexible Pavement Condition Rating Form	7
Key - Composite Pavement Condition Rating Form	8
Composite Pavement Condition Rating Form	9
Key - Jointed Concrete Pavement Condition Rating Form	10
Jointed Concrete Pavement Condition Rating Form	11
Key - CRC Pavement Condition Rating Form	12
CRC Pavement Condition Rating Form	13
APPENDIX A. Description of Distresses in Flexible Pavements	A-1
Raveling	A-2
Bleeding	A-4
Patching	A-6
Potholes/Debonding	A-8
Crack Sealing Deficiency	A-10
Rutting	A-12
Settlement	A-14
Corrugations	A-16
Wheel Track Cracking	A-18
Block and Transverse Cracking	A-20
Longitudinal Joint Cracking	A-22
Edge Cracking	A-24
Random Cracking	A-26

	Page
APPENDIX B. Description of Distresses in Composite Pavements	B-1
Raveling	B-2
Bleeding	B-4
Patching	B-6
Surface Disintegration or Debonding	B-8
Rutting	B-10
Pumping	B-12
Shattered Slab	B-14
Settlement	B-16
Transverse Cracking	B-18
Severity Level: Unjointed Base or Jointed Base	B-18
Extent Level: Jointed Base - Intermediate Transverse Cracking	B-20
Extent Level: Unjointed Base	B-20
Extent Level: Jointed Base-Joint Reflection Cracks	B-20
Longitudinal Cracking	B-22
Pressure Damage/Upheaval	B-24
Crack Sealing Deficiency	B-26
APPENDIX C. Description of Distresses in Jointed Reinforced Concrete or Jointed Concrete Pavements (JRC/JC Pavements)	C-1
Surface Deterioration	C-2
Popouts	C-4
Patching	C-6
Pumping	C-8
Faulting	C-10
Settlement	C-12
Transverse Joint Spalling	C-14
Joint Sealant Damage	C-16
Pressure Damage	C-18
Transverse Cracking	C-20
Longitudinal Cracking	C-22
Corner Breaks	C-24
APPENDIX D. Description of Distresses in Continuously Reinforced Concrete Pavements (CRCP)	D-1
Surface Deterioration	D-2
Popouts	D-4
Patching	D-6

	Page
Pumping	D-8
Settlements and Waves	D-10
Transverse Crack Spacing	D-12
Longitudinal Cracking	D-14
Punchouts or Edge Breaks	D-16
Spalling	D-18
Pressure Damage	D-20
 APPENDIX E. Sources of Photographs used in Appendices A - D	 E-1
List of Sources of Photographs.....	E-2

LIST OF FIGURES

Figure 1. Pavement Condition Rating (PCR) Scale	3
--	---

LIST OF PHOTOGRAPHS

		Page
APPENDIX A. Description of Distresses in Flexible Pavements		
Photo A-1.	Raveling in Flexible Pavement, Medium Severity	A-3
Photo A-2.	Raveling in Flexible Pavement, High Severity	A-3
Photo A-3.	Bleeding in Flexible Pavement, High Severity	A-5
Photo A-4.	Close-up view of Bleeding, High and Medium Severity	A-5
Photo A-5.	Patching in Flexible Pavement, High Severity	A-7
Photo A-6.	Patching in Flexible Pavement, High Severity	A-7
Photo A-7.	Pothole in Flexible Pavement, Medium Severity	A-9
Photo A-8.	Debonding in Flexible Pavement, Medium Severity	A-9
Photo A-9.	Crack Sealing Deficiency in Flexible Pavement, Unsealed Cracks	A-11
Photo A-10.	Crack Sealing Deficiency in Flexible Pavement, Cracks not sealed properly.....	A-11
Photo A-11.	Rutting in Flexible Pavement, Medium Severity	A-13
Photo A-12.	Rutting in Flexible Pavement, High Severity	A-13
Photo A-13.	Settlement, Low Severity	A-15
Photo A-14.	Settlement, Medium Severity	A-15
Photo A-15.	Corrugations in Flexible Pavement, Medium Severity	A-17
Photo A-16.	Wheel Track Cracking in Flexible Pavement, Med. Severity	A-19
Photo A-17.	Wheel Track Cracking in Flexible Pavement, High Severity	A-19
Photo A-18.	Block and Transverse Cracking in Flexible Pavement, Medium Severity	A-21
Photo A-19.	Block and Transverse Cracking in Flexible Pavement, High Severity	A-21
Photo A-20.	Longitudinal Joint Cracking in Flexible Pavement, Medium Severity	A-23
Photo A-21.	Longitudinal Joint Cracking in Flexible Pavement, High Severity	A-23
Photo A-22.	Edge Cracking in Flexible Pavement, Medium Severity	A-25
Photo A-23.	Edge Cracking in Flexible Pavement, High Severity	A-25
Photo A-24.	Random Cracking in Flexible Pavement, Medium Severity	A-27

LIST OF PHOTOGRAPHS

	Page
APPENDIX B. Description of Distresses in Composite Pavements	
Photo B-1. Raveling in Composite Pavement, Medium Severity	B-3
Photo B-2. Raveling in Composite Pavement, High Severity	B-3
Photo B-3. Bleeding, High Severity	B-5
Photo B-4. Close-up view of Bleeding, High and Medium Severity	B-5
Photo B-5. Patching in Composite Pavement, Medium Severity	B-7
Photo B-6. Patching in Composite Pavement, High Severity	B-7
Photo B-7. Surface Disintegration in Composite Pavement	B-9
Photo B-8. Debonding in Composite Pavement, Medium Severity	B-9
Photo B-9. Rutting, Medium Severity	B-11
Photo B-10. Rutting, High Severity	B-11
Photo B-11. Pumping in Composite Pavement, Medium Severity	B-13
Photo B-12. Pumping in Composite Pavement, High Severity	B-13
Photo B-13. Shattered Slab of Composite Pavement, High Severity	B-15
Photo B-14. Settlement in Composite Pavement, Medium Severity	B-17
Photo B-15. Unjointed Base, Transverse Cracking in Composite Pavement, Low Severity	B-19
Photo B-16. Unjointed Base, Transverse Cracking in Composite Pavement, High Severity	B-19
Photo B-17. Jointed Base, Reflection Cracking in Composite Pavement, Medium Severity	B-21
Photo B-18. Jointed Base, Reflection Cracking in Composite Pavement, High Severity	B-21
Photo B-19. Longitudinal Cracking in Composite Pavement, High Severity	B-23
Photo B-20. Pressure Damage/Upheaval in Composite Pavement, Medium Severity	B-25
Photo B-21. Crack Sealing Deficiency, Unsealed Cracks	B-27
Photo B-22. Crack Sealing Deficiency, Cracks not sealed properly	B-27

LIST OF PHOTOGRAPHS

	Page
APPENDIX C. Description of Distresses in Jointed Reinforced Concrete or Jointed Concrete Pavements (JRC/JC Pavements)	
Photo C-1.	Surface Deterioration in Jointed Concrete Pavement, Medium Severity C-3
Photo C-2.	Surface Deterioration in Jointed Concrete Pavement, High Severity C-3
Photo C-3.	Popout in Jointed Concrete Pavement, Plan and Cross-sectional Views C-5
Photo C-4.	Popouts in a Jointed Concrete PavementC-5
Photo C-5.	Patching in Jointed Concrete Pavement, Low Severity C-7
Photo C-6.	Patching in Jointed Concrete Pavement, High Severity C-7
Photo C-7.	Pumping in Jointed Concrete Pavement, High Severity C-9
Photo C-8.	Pumping in Jointed Concrete Pavement, Low Severity C-9
Photo C-9.	Sketch showing Faulting in Jointed Concrete Pavement C-11
Photo C-10.	Faulting in Jointed Concrete Pavement C-11
Photo C-11.	Settlements in Jointed Concrete Pavement, Medium SeverityC-13
Photo C-12.	Transverse Joint Spalling in Jointed Concrete Pavement, Low Severity C-15
Photo C-13.	Transverse Joint Spalling in Jointed Concrete Pavement, High Severity C-15
Photo C-14.	Joint Sealant Damage in Jointed Concrete Pavement C-17
Photo C-15.	Joint Sealant Damage in Jointed Concrete Pavement C-17
Photo C-16.	Pressure Damage in Jointed Concrete Pavement C-19
Photo C-17.	Pressure Damage in Jointed Concrete Pavement C-19
Photo C-18.	Transverse Cracking in Jointed Concrete Pavement, Low Severity C-21
Photo C-19.	Transverse Cracking in Jointed Concrete Pavement, High Severity C-21
Photo C-20.	Longitudinal Cracking in Jointed Concrete Pavement, Medium Severity C-23
Photo C-21.	Longitudinal Cracking in Jointed Concrete Pavement, Medium Severity C-23
Photo C-22.	Corner Break in Jointed Concrete Pavement, Medium Severity C-25
Photo C-23.	Corner Break in Jointed Concrete Pavement, High Severity C-25

LIST OF PHOTOGRAPHS

	Page
APPENDIX D. Description of Distresses in Continuously Reinforced Concrete Pavements (CRCP)	
Photo D-1. Surface Deterioration in CRC Pavement, Medium Severity	D-3
Photo D-2. Surface Deterioration in CRC Pavement, High Severity	D-3
Photo D-3. Popout in CRC Pavement, Plan and Cross-sectional Views	D-5
Photo D-4. Popouts in CRC Pavement	D-5
Photo D-5. Patching in CRC Pavement, Low Severity	D-7
Photo D-6. Patching in CRC Pavement, High Severity	D-7
Photo D-7. Pumping in CRC Pavement, Medium Severity	D-9
Photo D-8. Pumping, High Severity	D-9
Photo D-9. Settlement in CRC Pavement	D-11
Photo D-10. Transverse Cracks in CRC Pavement, Low Severity	D-13
Photo D-11. Transverse Cracks in CRC Pavement, Medium Severity	D-13
Photo D-12. Longitudinal Cracking in CRC Pavement, Medium Severity	D-15
Photo D-13. Longitudinal Cracking in CRC Pavement, High Severity	D-15
Photo D-14. Punchouts in CRC Pavement, Medium Severity	D-17
Photo D-15. Punchouts in CRC Pavement, High Severity	D-17
Photo D-16. Spalling in CRC Pavement, Medium Severity	D-19
Photo D-17. Spalling in CRC Pavement, High Severity	D-19
Photo D-18. An Example of Pressure Damage in Jointed Concrete Pavement, Pressure Damage in CRCP is similar to as shown above	D-21